

Man-Co Manufacturing Inc.

P.O. Box 13114, Salem, OR 97309
2470 Ewald Ave. SE 97312

AUGUST 14, 1984

BULLETIN #6-133-MC

MAIN BOOM ROCKER SHAFT FOR ROUND-UP RIDES MANUFACTURED BY FRANK HUBERZ & CO., INC. AND KILINSKI MFG. CO.

ATTENTION OWNERS OF ABOVE RIDES

A failure has been reported of the main boom rocker shaft on a Round Up manufactured by Frank Hubertz & Co., Inc. Although Man-Co Mfg., Inc. does not accept responsibility for rides built by Frank Hubertz & Co., Inc., or Kilinski Mfg., Co., we do feel that this is a potential safety problem sufficiently important to bring to your attention.

If you own a Round-Up, we strongly urge that you immediately inspect the main boom rocker shaft and the cylinder anchor shaft for cracks using Ultrasonic test. The test must be done by someone qualified to Level 2 ultrasonic testing. It is not necessary to disassemble the ride to perform the test on the main boom rocker shaft, or the cylinder anchor shaft.

THIS ULTRASONIC TEST MUST BE PERFORMED ANNUALLY.

This test was performed on a Round-Up at Man-Co Mfg., Inc. by an independent testing lab. Using a 2.5 MHz transducer on the end of the shaft. The instrumentation was set up to produce a strong reflection from the opposite end of the shaft and calibrated so that the shoulder on the far end of the shaft registered approximately 15-20% of full scale. This would cause a crack at or near the closer shoulder to register significantly. The test was repeated at the other end of the shaft. A sketch of the shaft is on Sheet 2.

If any indication of cracks is found, a 5 MHz transducer may be helpful in determining it's extent.

The test was not considered to be difficult by the testing lab.

If cracks are found in the shaft, it SHALL BE replaced immediately. Replacement shafts of the latest design may be purchased from Man-Co Mfg., Inc.

Visually inspect all welds for cracks. For verification, use magnetic particle testing.

Man-Co Manufacturing, Inc.

P. O. Box 13114, Salem, OR 97309
2470 Ewald Ave. SE 97302

ULTRASONIC TEST REQUIREMENTS

Ultrasonic testing shall be performed once a year (or as noted) on the following rides built by Frank Brubetz & CO.

Non-Folding Round-Up

1. Rocker shaft - see Dwg. BU-133MC sht. 2 of 3
2. Cylinder Anchor shaft - see Dwg. BU-133MC sht. 3 of 3
3. Spindle shaft (every two (2) years)

Folding Round-Up

1. Rocker shaft - see Dwg. BU-133MC sht. 2 of 3
2. Cyl. anchor shaft - see Dwg. BU-133MC sht. 3 of 3
3. Spindle (every two (2) years)

NOTE: If rocker shaft, cyl. anchor shaft or spindle have been replaced with new shaft with shrink collar, then Ultrasonic testing is required every one (1) year.

Ultrasonic Testing shall be performed every two (2) years on the following rides built by Kilmeka Mfg. Co.

Folding Round-Up

1. Rocker shaft
2. Cyl. anchor shaft
3. Spindle

Super Round-Up

1. Rocker shaft
2. Cyl. anchor shaft
3. Spindle

Hydraulic Paratrooper - park and portable

1. Spindle

Rim Drive Paratrooper - park and portable

1. Spindle

Standard Paratrooper - park and portable (built by Frank Brubetz & Co.)

1. Spindle

MAN-CO MANUFACTURING, INC.
QUALITY CONTROL PROCEDURE


ULTRASONIC INSPECTION OF STEEL

HAIR SPINBAL SHAFTS


G. C. J.
Revision D

10/26/98

Initiated by


L.J. Chamberlain
WESTPRO LABORATORY

Approved


Robert D. Rodewald
Quality Control Supervisor
Man-Co Manufacturing, Inc.

ULTRASONIC INSPECTION OF STEEL
MAIN SPINDAL SHAFTS

1. METHOD

1.1 Scope

This procedure establishes the minimum requirements for the pulse echo ultrasonic inspection of steel main spindal shafts by the contact longitudinal and angle beam techniques.

1.2 Principle

High frequency sound waves are induced into the material under test with the reflected sound wave forms being displayed on a cathode-ray tube. The soundness of the material is determined by analyzing the reflection patterns on the cathode ray tube.

2. APPARATUS

2.1 Electronic Apparatus

An ultrasonic pulsed reflection type of instrument shall be used for this inspection. The system shall have a minimum capability for testing at frequencies of 1 to 5 MHZ.

2.2 Search Units

Contact type search units shall be used for angle beam and/or longitudinal wave modes of testing. Search units shall be utilized at their rated frequencies. The maximum search unit dimension shall not exceed 1 inch, with a minimum frequency of 2.25 MHZ.

2.3 Couplant

A couplant, liquid or paste, having sufficient wetting properties to transmit ultrasonic vibrations from the transducer to the test surface such as, oil, glycerin, water, grease, or equivalent, shall be used.

2.4 Reference Standards

Reference standards made from acoustically similar material shall be used to establish a suitable base for determining the adjustment of the instrument used.

2.4.1 Reference blocks used as standards for the longitudinal beam examination shall contain flat bottom holes no larger than 8/64 inch diameter at approximate metal paths of $1/4T$, $1/2T$ and $3/4T$. (T = thickness)

Reference blocks used as standards for the angle beam examination shall contain a notch no greater than $1/8"$ deep $\times 1/2"$ long at a depth equal to or greater than the thickness of the material to be inspected.

2.4.2 When it is impractical to have reference blocks per paragraph 2.4.1 it is acceptable to calibrate on the test material itself, as described in Figure 1 and Figure 2.

2.5 Personnel Qualification

Personnel performing the test shall be certified to ASNT-TC-1A. Personnel who read and interpret indications and evaluate them shall be certified to ASNT-TC-1A Level II or equivalent.

3. GENERAL PROCEDURE

3.1 The procedure to be used is that of hand scanning the material by the contact longitudinal and angle beam method and introducing into it a beam of ultrasonic energy. Reflections of a portion of this energy will occur at the interfaces of material having different acoustical properties. The reflections are presented on a cathode ray tube and can be evaluated electronically against a predetermined standard. Rejectable areas are noted on each piece and tabulated on the inspection report.

3.2 Surface Condition of Test Material

The beam entry surface of the material shall be free of scale, dirt, grease, paint, or other foreign materials. The surface to be tested shall be uniformly smooth with a surface finish adequate to permit ultrasonic inspection at the required sensitivity.

3.3 Instrument Calibration

3.3.1 Longitudinal Beam Examination

When calibration is performed on a reference block the indication amplitude of all defects shall be adjusted to obtain a pulse height on the instrument screen of at least 70 percent of full scale.

When calibration is performed on the test material the instrument adjustment shall be as described in Figure 1.

3.3.2 Angle Beam Examination

When calibration is performed on a reference block the indication amplitude of the reference notch shall be adjusted to obtain a pulse height on the instrument screen of at least 70 percent of full scale.

When calibration is performed on the test material instrument adjustment shall be as described in Figure 2.

3.3.3 After instrument calibration and the test of any material is initiated, additional adjustment of the instrument shall not be permitted without recalibration.

3.4 Scanning Surfaces

3.4.1 Longitudinal and angle beam examination shall be performed on the test material as described in Figure 3.

3.4.2 A calibration standard shall be referenced at the beginning and end of each test piece or at intervals not exceeding 1 hour.

3.5 Interpretation of Results

Material is unacceptable if longitudinal and/or angle beam examination results show one or more reflections greater in amplitude than the indication from the calibration defect or reference line and are not associated with the geometric configuration.

3.6 Test Reports

Test records shall be maintained by the testing organization for a minimum period of three years following completion of order. The following data shall be recorded on the test report.

3.6.1 Specific written test procedure and revision utilized for performing the test.

3.6.2 Transducer description, instrument and ultrasonic frequency employed.

3.6.3 Reference standard description.

3.6.4 Location and identification of rejectable indication in material. (Sketch to be included)

3.6.5 Customer identification and location of material and equipment serial number.

3.6.6 Name and location of testing organization.

3.6.7 Date of Test

3.6.8 Signature of Operator

QC-U1-I-Rev 0
Page 4 of 6




Figure 1

Calibration on test piece for longitudinal Beam examination

Notes for Figure 1:

1. A 3/4" Diameter - 5 MHZ Transducer is recommended.
2. The search unit shall be placed on center of shaft area (A) and adjust second back reflection to 100%.
3. Move transducer toward edge of shaft (A) step 1 should appear to be approximately 25% of the total perimeter and adjust to the average.
4. The search unit shall be placed on an indication free area (B) of the shaft being tested and the first back reflection shall be set between 75 to 90% of full screen height.




Figure 2

Calibration on test piece for Angle Beam examination

Notes for Figure 2:

1. A 1/2" x 1/2" - 2.25 MHZ - 45° angle beam search unit is recommended.
2. The search unit shall be placed on an indication free area (C) and the instrument shall be adjusted to obtain a signal amplitude of 40 to 60% full screen height from the shaft step 1.



Figure 3

1. Longitudinal Beam Examination

- A. Area (A) and (D) shall be scanned 100%.


- B. Area (B&C) shall be scanned 100%.

2. Angle Beam Examination

- A. Area (B&C) shall be scanned 100% in two axial directions 180° opposed.

Useful Information:

Basic Shaft Configuration



I. Material: Carralloy Steel.
Longitudinal Velocity = 2.31" per second $\times 10^5$

II. Transducer Beam Divergence in Steel:

1" Dia. Transducer @ 1 MHZ = 30° or 3" per ft.

1" Dia. @ 2.25 MHZ = 14° or 1-1/2" per ft.


1" Dia. @ 5.0 MHZ = 6° or 5/8" per ft.

.750" Dia. @ 1 MHZ = 45° or 4-1/2" per ft.

.750" Dia. @ 2.25 MHZ = 20° or 2-1/8" per ft.

.750" Dia. @ 5.0 MHZ = 9° or 7/8" per ft.

Front Face





Paratrooper

MAN-CO MFG., INC.

2725 19th Street S.E. • P.O. Box 13114 • Salem, OR 97309 U.S.A. • (503) 362-2341

BULLETIN: BU-135 MC

DATE: 9/20/88

ANNUAL INSPECTION OF MAIN SPINDLE SHAFTS, ROCKER SHAFTS, CYLINDER ANCHOR SHAFTS

ATTENTION ALL ROUND-UP, PARATROOPER AND FIREBALL OWNERS

Due to recent failures in the spindle and rocker shafts of the Round-Up, and since the Paratrooper and Fireball rides manufactured by Frank Hrubetz Co. and Kilinski Mfg. (KMC) use the same shafts, Man-Co Manufacturing in cooperation with the recommendations of the Consumer Products Safety Commission feel the following steps should be taken.

These shafts need to be tested annually before the start of each season. Please see the Change Notice of the quality control procedures enclosed. (QC-JI-I-Rev. 3)

If any cracks are found, then the shafts are to be replaced immediately.

Maintenance records should be maintained and reviewed to determine the level of maintenance and frequency of the inspections of the individual ride. This is to insure that the rides are periodically inspected and safe.

Man-Co Manufacturing, as an exclusive manufacturer of replacement parts for the original Frank Hrubetz, and Kilinski Mfg. rides, can recommend but not mandate that these procedures be adhered to. However, we feel that this is a most important step for the protection of the ride owners and customers.

ULTRASONIC TEST REQUIREMENTS

Ultrasonic testing shall be performed once every year on the following rides built by Frank Hrubetz & Co., Kilinski Mfg. Co., and Man-Co Manufacturing, Inc.

Non-Folding Round-Jo

1. Rocker shaft - see dwg. BU-133MC sht. 2 of 3
2. Cylinder anchor shaft - see Dwg. BU-133 sht. 3 of 3
3. Spindle shaft

Folding Round-Jo

1. Rocker shaft - see Dwg. BU-133MC sht. 2 of 3
2. Cylinder anchor shaft - see Dwg. BU-133MC sht. 3 of 3
3. Spindle shaft

Super Round-Jo

1. Rocker shaft
2. Cylinder anchor shaft
3. Spindle shaft

Hydraulic Paratrooper - park and portable

1. Spindle shaft

Rim Drive Paratrooper - park and portable

1. Spindle shaft

Standard Paratrooper - park and portable

1. Spindle shaft

Fireball - portable

1. Spindle shaft

ULTRASONIC INSPECTION OF STEEL

MAIN SPINDLE SHAFTS

1. METHOD

1.1 Scope

This procedure establishes the minimum requirements for the pulse echo ultrasonic inspection of steel main spindle shafts by the contact longitudinal beam techniques for the detection of inservice stress cracking.

1.2 Principle

High frequency sound waves are induced into the material under test with the reflected sound wave forms being displayed on a cathode-ray tube. The soundness of the material is determined by analyzing the reflection patterns on the cathode ray tube.

2. APPARATUS

2.1 Electronic Apparatus

An ultrasonic, pulsed, reflection type of instrument shall be used for this inspection. The system shall have a range capability for testing at frequencies of 1 to 5 MHz.

2.2 Search Units

Contact type search units shall be used for the inspection. Search units shall be utilized at their rated frequencies. The maximum search unit dimension shall not exceed 1 inch, with a minimum frequency of 2.25 MHz.

2.3 Couplant

A couplant, liquid or paste, having sufficient wetting properties to transmit sound waves from the transducer to the test surface such as, oil, glycerin, water, grease, or equivalent, shall be used.

2.4 Reference Standards

Reference standards made from acoustically similar material shall be used to establish a suitable base for determining the adjustment of the instrument used.

- 2.4.1 Reference blocks used as standards for the longitudinal beam examination shall contain flat bottom holes no larger than 8/64 inch diameter at approximate metal paths of 1/4T - 1/2T and 3/4T. (T = Thickness)
- 2.4.2 When it is impractical to have reference blocks per paragraph 2.4.1, it is acceptable to calibrate on the test material itself, as described in Figure 1.

2.5 Personnel Qualification

Personnel performing the test shall be certified to ASNT-TC-1A. Personnel who read, interpret and evaluate indications shall be certified to ASNT-TC-1A Level II or equivalent.

3. GENERAL PROCEDURE

- 3.1 The procedure to be used is that of hand scanning the material by the contact longitudinal beam method and introducing into it a beam of ultrasonic sound waves. Reflections of a portion of this energy will occur at the interface of materials having different acoustical properties. The reflections are displayed on a cathode ray tube and can be evaluated against a predetermined standard. Areas with indications are noted on each piece and tabulated on the inspection report.

3.2 Surface Condition of Test Material

The beam entry surface of the material shall be free of scale, dirt, grease, paint, or other foreign materials. The surface to be scanned shall be uniform with a surface finish adequate to permit ultrasonic inspection at the required sensitivity.

3.3 Instrument Calibration

3.3.1 Longitudinal Beam Examination

When calibrating the instrument using a reference block, the indication amplitude of all defects shall be adjusted to obtain a pulse height on the instrument screen of at least 70 percent of full scale.

When calibration is performed using the test material, the instrument adjustment shall be as described in Figure 1.

- 3.3.2 After final instrument calibration and the test is initiated, further adjustment of the instrument shall not be permitted without recalibration.

3.4 Scanning Surfaces

- 3.4.1 Longitudinal beam examination shall be performed on the test material as described in Figure 2.
- 3.4.2 The instrument calibration shall be checked using a reference standard prior to and after each piece is tested or at intervals not exceeding 1 hour.

3.5 Interpretation of Results

Test part is unacceptable if longitudinal examination results show one or more reflections greater in amplitude than the indication from the calibration defect or reference line and are not associated with the geometric configuration.

3.6 Test Report

Test records shall be maintained by the testing organization for a minimum of three years following completion of order. The following data shall be recorded on the test report.

- 3.6.1 Specific written test procedure and revision utilized for performing the test.
- 3.6.2 Transducer description, instrument and ultrasonic frequency employed.
- 3.6.3 Reference standard description.
- 3.6.4 Location and identification of rejectable indication in material. (Sketch to be included)
- 3.6.5 Customer identification and location of material and equipment serial number.
- 3.6.6 Name and location of testing organization.
- 3.6.7 Date of Test
- 3.6.8 Signature of operator and level of certification.
- 3.6.9 Signature of interpreter and level of certification.




Figure 1

Calibration on test piece for Longitudinal Beam examination

Notes for Figure 1:

1. A 3/4" Diameter - 5 MHz Transducer is recommended.
2. The search unit shall be placed on center of shaft area (A) and adjust second back reflection to 100%.
3. Move transducer towards edge of shaft (A)
 - 3.1 Step 1 should appear to be approximately 25%.
 - 3.2 If not, scan the perimeter and adjust to the average.





Figure 2

1. Longitudinal Beam Examination

- A. After calibration per Figure 1, areas (A) and (B) shall be scanned 100%.


Useful Information :



- I. Material: Carralloy Steel Rim Drive Paratrooper
Longitudinal Velocity: $2.31'' \text{ per second} \times 10^5$ Serial No. 300 & on.
- II. Transducer Beam Divergence in Steel:



1" Dia. Transducer @ 1 MHZ	= 30° or $3'' \text{ per ft.}$
1" Dia. " @ 2.25 MHZ	= 14° or $1-1/2'' \text{ per ft.}$
1" Dia. " @ 5.0 MHZ	= 6° or $5/8'' \text{ per ft.}$
.750" Dia. "	@ 1 MHZ = 45° or $4-1/2'' \text{ per ft.}$
.750" Dia. "	@ 2.25 MHZ = 20° or $2-1/8'' \text{ per ft.}$
.750" Dia. "	@ 5.0 MHZ = 9° or $7/8'' \text{ per ft.}$

Front Face





Useful Information:

BASIC SHAFT CONFIGURATIONS



RIM DRIVE PARATROOPER
SERIAL NO. 301 to 396





RIM DRIVE PARATROOPER
SERIAL NO. 397 on up



Useful Information:

QC-UI-I-Rev. 3
Page 8 of 23

BASIC SHAFT CONFIGURATIONS



STANDARD PARATROOPERS
SERIAL NO. 500 and on





SPITFIRE AND
STANDARD PARATROOPERS
PRIOR TO 1960.



Useful Information:

QC-UI-I-Rev. 3
Page 9 of 23

BASIC SHAFT CONFIGURATIONS




SUPER ROUND-UP
SERIAL NO. 200S & UP




FIREBALL - SERIAL NO. F701
AND UP
HYDRAULIC PARATROOPER
SERIAL NO. 800 & UP

BASIC SHAFT CONFIGURATIONS





NON-FOLDING ROUND-UP
SERIAL NO. 400 & 4400




FOLDING ROUND-UP
SERIAL NO. 200 & 2200

BASIC SHAFT CONFIGURATIONS



SUPER ROUND-UP
SERIAL NO. 220 & UP




MAN-CO. MFG. INC.

P.O. BOX 13114
SALEM, OR 97309

PIVOT SHAFT - 40FT. ELEVATED-UP


REV	DATE	DESCRIPTION	DATE	DRAWN BY	NO.
A	3-17-89	SHOW SHRINK COLLARS	4-12-89	M.D.Z.	SK-41285



MAN-CO. MFG. INC. P.O. BOX 13114
SALEM, OR 97308

ANCHOR-SHAFT 90FT FOUND-UP

REV	DATE	DESCRIPTION	DATE 9-12-85	DRAWN BY M.O.Z.	NO. SE-01585
A	3-17-87	SHOW SHRINK COLLAR		SCALE	




QC-UI-I-Rev. 3
Page 14 of 23

MAN-CO. MFG. INC.

P.O. BOX 13114
SALEM, OR 97308

30' FOLDING POLO/POCKEY SHAFT W/SHRINK COLLAR	
DATE 3-7-84	DRAWN BY M.C.Z
SCALE	NO. SK-378A





MAN-CO MFG., INC.

2725 19th Street S.E. • P.O. Box 13114 • Salem, OR 97309 U.S.A. • (503) 362-2341

BULLETIN: BU-135 MC

DATE: 9/20/88

ANNUAL INSPECTION OF MAIN SPINDLE SHAFTS, ROCKER SHAFTS, CYLINDER ANCHOR SHAFTS

ATTENTION ALL ROUND-UP, PARATROOPER AND FIREBALL OWNERS

Due to recent failures in the spindle and rocker shafts of the Round-Up, and since the Paratrooper and Fireball rides manufactured by Frank Hrubetz Co. and Kilinski Mfg. (KMC) use the same shafts, Man-Co Manufacturing in cooperation with the recommendations of the Consumer Products Safety Commission feel the following steps should be taken.

These shafts need to be tested annually before the start of each season. Please see the Change Notice of the quality control procedures enclosed. (QC-UI-I-Rev. 3)

If any cracks are found, then the shafts are to be replaced immediately.

Maintenance records should be maintained and reviewed to determine the level of maintenance and frequency of the inspections of the individual ride. This is to insure that the rides are periodically inspected and safe.

Man-Co Manufacturing, as an exclusive manufacturer of replacement parts for the original Frank Hrubetz, and Kilinski Mfg. rides, can recommend but not mandate that these procedures be adhered to. However, we feel that this is a most important step for the protection of the ride owners and customers.

ULTRASONIC TEST REQUIREMENTS

Ultrasonic testing shall be performed once every year on the following rides built by Frank Hrubetz & Co., Kilinski Mfg. Co., and Man-Co Manufacturing, Inc.

Non-Folding Round-Up

1. Rocker shaft - see dwg. BU-133MC sht. 2 of 3
2. Cylinder anchor shaft - see Dwg. BU-133 sht. 3 of 3
3. Spindle shaft

Folding Round-Up

1. Rocker shaft - see Dwg. BU-133MC sht. 2 of 3
2. Cylinder anchor shaft - see Dwg. BU-133MC sht. 3 of 3
3. Spindle shaft

Super Round-Up

1. Rocker shaft
2. Cylinder anchor shaft
3. Spindle shaft

Hydraulic Paratrooper - park and portable

1. Spindle shaft

Rim Drive Paratrooper - park and portable


1. Spindle shaft

Standard Paratrooper - park and portable

1. Spindle shaft

Fireball - portable

1. Spindle shaft



QC-UI-I-Rev. 3
Page 18 of 23


MAN-CO. MFG. INC.

P.O. BOX 13114
SALEM, OR 97303

SCALE: NONE	DATE: 3-14-89	DRAWN BY: SWJ
----------------	------------------	------------------

30' FOLDING ROUND-UP ANCHOR
SHAFT

SK 314890



MAN-CO. MFG. INC.

P.O. BOX 12514
SALEM, OR 97308

SCALE: NONE	DATE: 3-14-84	DRAWN BY SWJ
----------------	------------------	-----------------

RIM DRIVE PARA BOOM


SK 314891



MAN-CO. MFG. INC.

P.O. BOX 13114
SALEM, OR 97303

SCALE: NONE	DATE: 3-14-89	DRAWN BY: SWJ
SPINDLE SHAFT ON BOOM		HYD. PARA.
		SK 31489




MAN-CO. MFG. INC.

P.O. BOX 12514
SALEM, OR 97308


TOLERANCES: UNLESS NOTED			DRAWN BY: SWJ
DECIMALS	FRACTIONS	ANGLES	DATE: 3-14-89
.000 ± .015	.000 ± .010	.000 ± .005	SCALE: NONE

FIREBALL SPINDLE SHAFT


REV.	DATE	DESCRIPTION	NEXT ASSEMBLY	REVISION	DRAWING NO.	A
		REVISIONS			SK-314892	



MAN-CO. MFG. INC.	
P.O. BOX 13114 SALEM, OR 97302	
MAIN BOOM ROCKER SHAFT	
DATE 5-14-04	SHAFT DIMENSIONS
DRAWN BY M.O.Z	PREVIOUS TO
SCALE —	SHAFTS WITH
NO. SHRINK COLLARS	



MAN-CO. MFG. INC.		P.O. BOX 12514 SALEM, OR 97303
CYL. ANCHOR SHAFT		
DATE	8-14-84	
DRAWN BY	M.W.Z	
SCALE	—	
NO.		SHAFT DIMENSIONS PREVIOUS TO SHAFTS WITH SHRINK COLLARS



EMERGENCY ALERT ON THE RIDE, "ROUND-UP"
(by Manco, Hrubatz Mfg, or Kilinaki Mfg)

In early June 1993, a Round-Up ride experienced a failure of a weld located on the shrink collar on the main center spindle (two drawings are attached for reference). This is the first known occasion for this style of shaft to fail since the manufacturer's Bulletin requiring replacement of an earlier system.

The weld should be visually inspected immediately and periodically thereafter.

In doing so, the power for the ride needs to be turned off, and the brush holder located at the end of the main boom removed. Once this is completed, the weld that ties the (1) shrink collar to the (2) steel plate needs to be cleaned and inspected. See the first of the drawings for areas marked (1) and (2). Should a visual indication be found, the ride needs to be closed and the K&K Insurance Group, Loss Control Division, notified immediately (219-455-5709).

06/93/59

Presented in the interest of helping K&K clients improve their insurability

HOKIULUIKE

NOV 8 1996

NOV 26 1996

13:08 NO. 002 P.O.

