

CARES Notification

*This document contains technical information provided by a CARES member agency.
This document is FOR INFORMATION ONLY.*

Subject: Cracking near gondola suspension bearing

Ride(s) affected: Huss Top Spin

Date: August 17, 2011

Source: Leisure Technical Consultants Limited (LTC; <http://www.ltci.co.uk/>)

LTC has provided the following photographs of cracks found on a Huss Top Spin. The photographs were supplied by a ride inspection body in the UK without comment or further information.

Similar cracking has been observed on a ride operating in Canada. That ride has been closed pending an engineering review.

The manufacturer has been contacted, but as of this date has NOT issued a bulletin, repair information, or official statement.





