ZAMPERLA INC. 49 Fanny Road Parsippany, New Jersey 07054-6545

USA

Future Action To Be Taken:

Phone: 973 334 8133 Fax: 973 334 6880

Bulletin No: 2000 BS1

Release Date: 10/09/2000

Effective Date: 10/09/2000

Supersedes:


Completion Date: As soon as possible

Page: 1of 2

SERVICE BULLETIN

Ride Manufacturer: Zamperla Inc.	Affected Production Dates: All
Ride Name: Barnstormer	Affected Serial Nos.: All
Model Number: Barnstormer	,
Abstract Of Issue:	
A hazard exists in a guard of the gondolas.	
Reason For Release:	
	nder the guard on each gondola in one corner. A small child's can fit through the opening.
Action To Be Taken:	
	uards as indicated in the attached photo. There is one for the a and one for the right gondola.
Detail Of Issue:	
Attached photo (page 2)	

None.



ZAMPERLA INC. 49 Fanny Road Parsippany, New Jersey 07054-6545

USA

Phone: 973 334 8133 Fax: 973 334 6880

Bulletin No: 2002 BS1

Release Date: 12/6/2002

Effective Date: 12/6/2002

Supersedes:

Completion Date: As soon as possible

Page: 1 of 2

SERVICE BULLETIN

	A THE STATE OF THE SECOND OF THE SECOND
Ride Manufacturer: Zamperia SPA	Affected Production Dates: All
Ride Name: Barnstormer	Affected Serial Nos.: All
Model Number: Barnstormer	

Abstract Of Issue:

A crack has been detected in a weld of an internal reinforcing plate of the gondola attaching arm.

Reason For Release:

Same

Action To Be Taken:

Visually inspect the side surface of the gondola attaching arms in the area indicated on page 2. If there are any signs of cracked paint contact Zamperla immediately.

Detail Of Issue:

Page number 2 "Diagram of the gondola attaching arm".

Future Action To Be Taken:

Visually inspect the side surface of the gondola attaching arms on a weekly basis. If there is any signs of cracked paint, contact Zamperla immediately.

Bulletin 2002 BS1 Page 2 of 2

