

| | |
|-----------------|-----------------|
| Bulletin No.: | 8 |
| Release Date: | August 17, 2018 |
| Effective Date: | August 17, 2018 |
| Supersedes: | none |
| Issued by: | A. Beck |
| Checked by: | E. Berra |
| Page: | 1 of 2 |

SERVICE BULLETIN

Affected Park: DOLLYWOOD
Affected Ride: WING COASTER
Ride Name: WILD EAGLE

Item: Mobile Magnetic Brake – Air Cylinder Attachment Bracket

Abstract of Issue:
Inspection of the aluminum bracket as per Detail of Issue.

Reasons for Release:
Cracks were discovered at the junction of the aluminum bracket's base plate.

Actions to be taken:

- 1) Close visual inspection of all the air cylinder attachment brackets of the mobile magnetic brakes, within 30 days as per Detail of Issue.
Brackets showing indication shall be replaced.
- 2) A monthly visual inspection of this bracket shall be included in the regular maintenance schedule.

Completion:
Within 30 days for item 1).

| | |
|-----------------|-----------------|
| Bulletin No.: | 8 |
| Release Date: | August 17, 2018 |
| Effective Date: | August 17, 2018 |
| Supercedes: | none |
| Issued by: | A. Beck |
| Checked by: | E. Berra |
| Page: | 2 of 2 |

Detail of issue:

