

GARBRICK MANUFACTURING, INC.

LEWIS H. GARBRICK
LEWIS A. GARBRICK
CENTRE HALL, PENNSYLVANIA 16828
PHONE 814-364-1403



July 3, 1991

TO WHOM IT MAY CONCERN:

Due to the age of the Ground-model Merry Mixers, it is recommended that Non-destructive Testing be performed as a safety precaution on the spindles which hold the seats.

Very truly yours,

GARBRICK MANUFACTURING, INC.

Lewis A Garbrick
Vice-President

RECEIVED

JUL 05 1991

DEPARTMENT OF LABOR
CARNIVAL & AMUSEMENT RIDE
INSPECTION DIVISION

Scale 1" = 1'-0"

SEAL 10 MB

WINDS KIT 1" O.D. TUBING



cut 2" dia
rod. 2" dia by
provide

1/2" 1.0. Top of 7" wall
89

1/2" STRIP

SECTION A-A
Scale: 2" = 1'-0"

Roller Bearing
Timken No 3982



1/4"

1/8"

1/2" 1.0. 1993
1/2" 1.0. 1993
30"



ILLINOIS DEPARTMENT OF LABOR

Shinae Chun
Director

July 17, 1991

Mr. Lewis A. Garbrick
Garbrick Manufacturing Inc.
Centre Hall, Pennsylvania 16828

Dear Mr. Garbrick:

I received your letter of July 3rd recommending a nondestructive test on the Merry Mixer seat spindles. I have several questions regarding the recommendation.

At what frequency is the test to be performed? Is it to be performed only once, is it to be performed annually, or is it to be done at some other interval time?

What is the recommended test method: ultrasonic, magnetic particle, x-ray or other?

Also, the print provided does not reproduce well. Is it possible to get a legible sketch/drawing for the NDT technician to work from?

Your assistance in resolving these matters will be appreciated.

Sincerely,

A handwritten signature in cursive script that reads "Carl Kimble".

Carl Kimble, P.E.
Chief Inspector
Carnival & Amusement Rides
Telephone: 217-782-9347