



Great Coasters International,
Inc.

2627 State Rt 890
Sunbury, PA 17801
USA
Phone: 570-286-9330
Fax: 570-286-4272
info@greatcoasters.com

Bulletin No.:	17121170
Release Date:	12/12/2017
Effective Date:	IMMEDIATE
Supercedes:	NONE
Completion Date:	AS REQUIRED

Page:	1 of 1
-------	--------

SERVICE BULLETIN

Ride Manufacturer:	Great Coasters Int., Inc.	Affected Production Dates:	1999-2017
Ride Name:	Varies	Affected Serial Nos.:	N/A
Model Number:	Varies		

Abstract of Issue:

GCII is defining ride operating conditions for the ride.

Reason for Release:

With more parks running during the winter months, some parks have recently valleyed their rides.

Action To Be Taken:

It should be noted with your park operations team and maintenance personnel that if the weather conditions begin to encroach on any of the following, steps should be taken to be sure the ride will not valley. Should your ride become valleyed either with or without guests on the train, appropriate steps should be taken to mitigate the problem and GCII personnel should be at least made known of the condition.

Detail Of Issue:

Please reference section 1.7 and 12 in your ride manual regarding general ride operation conditions.

Do not ever operate the ride in the following conditions

- Thunderstorms
- Lightning
- Heavy rain
- Thick fog
- Snow or ice (present on the track)
- Flooding conditions
- Wind in excess of 34 mph [15.0 m/s]
- Low operating temperatures [below 32°F [0°C]]

If operating the ride at temperatures below 36°F [2°C], bleed all airlines of any condensation prior to operation.

When operating the ride below 50°F [10°C], verify appropriate lubrication of the track. Also, use light grease on the guide wheels and fill the road wheels with light oil. Refer to the separate Train Manual. This lighter grease should have good low temperature mobility

Cycle times should be within normal parameters prior to operation with guests. Please review cold weather operating times vs. normal operational times during the season.