



ATTENTION SCAT OWNERS

THE MAIN ARM HINGE PINS (FIG. 'A' IN THE ILLUSTRATION) ARE MADE FROM STRESSPROOF STEEL (MIN. YIELD 90,000 PSI). IF THESE PINS EVER NEED TO BE REPLACED, THE SAME TYPE MATERIAL MUST BE USED.

Do NOT Use MILD STEEL PINS!

PLEASE ATTACH THIS TO YOUR SCAT MAINTENANCE MANUAL FOR FUTURE REFERENCE.

SENT TO ALL EXISTING SCAT OWNERS BY CERTIFIED MAIL 9-2-76.

SENT TO ALL STATE SAFETY BOARDS 9-3-76

VENTURE RIDE MFG, GREER, S.C.				
DRAWN	DATE	SCALE	REQ'D	PART NUMBER
BHW				VRM 4504



Venture
Ride Mfg., Inc.

JERRY L. BARBER, President

July 11, 1983

PLEASE ADD TO YOUR SCAT MANUAL

TO ALL SCAT OWNERS:

Because of the motion and speed of your SCAT ride, there is enough centrifugal force to hold the riders against the cage. It is possible for a rider to try to climb up the side of the cage, lean out and suffer serious injury.

Enclosed are some signs to place inside the tubs, on the straight side, telling riders to keep their feet on the floor at all times. Additionally, we recommend that you tell your operator to keep watch on the passengers and, if at any time they see someone attempt to take their feet off the floor, to stop the ride immediately. This should be a standard procedure and would be an extra precaution to prevent any accidents.

Sincerely,

Jerry L. Barber
President

JLB/md