



Issuing Entity:
Larson International Inc.
P.O. Box 638
Plainview, TX 79073-0638
U.S.A.
Phone 806-293-1353
Fax 806-293-5215
www.larsonintl.com

Bulletin No.: L16-004
Release Date: 3/16/16
Effective Date: Immediately
Supercedes: N/A
Completion Date: N/A
Page: 1 of 2

NOTIFICATION

Ride Manufacturer: Larson International Inc. **Affected Production Dates:** All
Ride Name: FLYING SCOOTERS **Affected Serial Nos.:** 1-26,30

Abstract Of Issue: Monitor and address potential corrosion in the ride vehicles.

Reason for Release: Corrosion has been found on the inside of the ride vehicles.

Action To Be Taken: Annual inspection of the inside of the ride vehicles and address corrosion as necessary to prevent reduction of steel thickness. Adding drain holes in the rear corners of each vehicle may help prevent future water entrapment (see drawing page 2).

Detail Of Issue:

Vehicle drain holes drawing on page 2.



Larson International Inc. issues notifications for the benefit of owners of amusement rides manufactured by Larson International, Inc. As a service to the industry, and in the interest of employee and public safety, Larson International, Inc. also issues notifications for the benefit of owners of amusement ride equipment for which the manufacturer no longer exists such as LMC, Inc. and Hi-Roller Company. In doing so, Larson International, Inc. does not assume liability for losses associated with amusement ride equipment built by manufacturers other than Larson International, Inc.

