

Customer Support

Maurer Rides GmbH

Frankfurter Ring 193
80807 München

Service Bulletin 002/06

August 2006

Ride: Compact Spinning Coaster, SC 2000, SC 3000
Part: Lock

We regularly hold courses concerning the vehicles of the "Spinning Coaster" on our premises in Munich training our world-wide customers. During these courses we have come to know that the adjustment of the fine teeth (see pos. 20 and 90 on page 860) of the lock of our vehicles can be made easier.

We therefore will replace the latch (pos. 20) with two teeth by a latch with one tooth (pos. 90). A better visibility and therefore an easier adjustment will be the big advantage.

This results in more standardization, meaning that in the future there will be only one part for pos. 20 and 90. This part will have one tooth and will bear the item-no. 83560. From now on we will not supply the latch with 2 teeth (item-no. 81576) anymore.

Please note that there is no need for an immediate replacement of the parts. You can do the exchange during your normal maintenance of wear and tear.

The safety of the vehicles is not affected in any way. On the contrary: The easier adjustment will raise the safety standard.

We recommend to send us a confirmation after the execution of the replacement-work to complete our and your files.

Munich, 2006-08-07

Guido Bäuerle
Manager Customer Support

