

CARES Notification

*This document contains technical information provided by a CARES member agency.
This document is FOR INFORMATION ONLY.*

Subject: Main Mast Cracking

Ride(s) affected: Mondial Top Scan

Date: January 12, 2012

Source: Leisure Technical Consultants Limited (LTC; <http://www.ltci.co.uk/>)

An inspector in the UK has provided the following information regarding a crack found on an “older” Mondial Top Scan:



The cracking is on the main mast just above the pivot section where it attaches onto the trailer, as indicated on the following drawing. There may have been a previous weld repairing repair in this region but at this stage that cannot be confirmed. The surface opening width apparently was big enough to be able to push a thumbnail into it, the overall length of the crack being approximately 130 to 150 mm.

