



| | |
|----------------------------|--------------------------|
| 1583 East Silver Star Road | Bulletin No: 001 |
| #280 | Release date: 10/01/04 |
| Ocoee, Florida 34761 | Effective date: 10/01/04 |
| (407) 436-1544 | Supersedes: N/A |
| | Completion date: |
| | Page 1 of 1 |

| | |
|---|-------------------------------|
| Ride Manufacturer: Reaction Attractions | Affected Production date: ALL |
| Ride Name: 30' x 40' Obstacle Course | Affected serial numbers: ALL |

The 30'x 40' obstacle courses must have closed any gaps in connection of travel lanes. This will ensure the safety of the participants as there will be no chance of any legs or arms falling between the lanes.

Reason for release:

To prevent injury of participants resulting from wayward travel through obstacle courses in which lanes are not fastened with eyelets or coversheets from end to end.

Action to be taken:

Contact Reaction Attractions if you own a 3 lane obstacle course, and the lanes are not connected from front to back with eyelet for bungee ties. Reaction Attractions will supply you with a coversheet to close any gaps in lanes of obstacle course with instructions on how to apply them.

1583 East Silver Star Road
#280
Ocoee, Florida 34761