



WMI INDUSTRIES, LTD.

November 18, 1993

Lowell Parish
FLORIDA DEPT. OF AGRICULTURE
BUREAU OF FAIRS
3125 Conner Blvd. Bldg. 4
Tallahassee, Fl 32399-1650

Fax: 904-488-9023

RE: Replacing the pins with a bolt on Gravitron & Starship 2000 models.

Dear Sir,

There is no problem with replacing the pin with a bolt as long as the bolt is a grade 5 3/4" diameter bolt and nut.

The corner pin can be replaced with a bolt with a double nut locking system and can also be used in the corner of the panel.

If you have any questions, please contact me.

Sincerely,

Dale Colerick