



February 25, 1998

To Whom It May Concern:

The question arose about the safety of operation of a Gravitron that apparently has the cam followers, or bearings, mounted to the back of the seats froze up and not turning freely.

While this will diminish the effect and thrill of the ride, this alone should not be a safety concern.

The operator should be cautioned to watch passengers and not allow them to walk their way up the seat while spinning at full speed.

James R. Merrell



Wisdom Industries, Ltd.