ZAMPERLA INC. 49 Fanny Road Parsippany, New Jersey 07054-0598 USA

Phone: 973 334 8133 Fax: 973 334 6880

Bulletin No: 97 SA1 Release Date: 12/8/97

Effective Date: 12/8/97

Supersedes:

Completion Date: Before riding passengers

Page: 1 of 2


SERVICE BULLETIN

Ride Manufacturer: Zamperla Inc.	Affected Production Dates: All
Ride Name: Samba	Affected Serial Nos.: All
Model Number: Samba	
Abstract Of Issue: Cracks have been found in the welds loca center frame structure. See	ated at the center column base plate junction and in the lower areas indicated on the accompanying diagram.
Reason For Release:	Same.
Action To Be Taken: Magnetic particle	testing by a certified NDT technician
Detail Of Issue: If cracks have been detected in the above for Noti	mentioned welds and confirmed, please contact Zamperla Inc. fication of repair procedure.
Future Action To Be Taken: Magnetic particle testi	ing by a certified NDT technician annually.

1	ಽಟ≡	HL	کلا)∀:	m	۲V	N.S	30	IJĦ	Į)	(3k	į.	SUN	V
	Ì	Δı	Ą	Ø	In		5	Y	1	٥	10	1		
	[\T	٦,	3	0	M	X.	σţ	1	<u>ال</u>	Ľ	tL			<i>#</i>
				30 me			7.7			7 (*) 10	14.V	- 32	-N. A	. 4.

ambiraa Yurmbera

A.	چ	1) ə
gran.	75.4 -777)	(II)	AT AT
	3457 W		<u> </u>



SOTEM SEWWIE METE

ened the lower frame welds here