

Issuing Entity:

Ice Bumper Cars International 611 2nd Ave Longmont CO 80501 www.icebumbercars.com Bulletin No: 001

Release Date: 11/23/2019

Effective Date: 11/23/2019

Supersedes: NA

Completion Date: 12/6/2019

Page: 1 of 1

Service Bulletin

Ride Manufacturer: Ice Bumper Cars Internationa	Affected Production Dates: All
Ride Name: Ice Bumper Cars	Affected Serial Numbers: All
Model Number: Gen 1, Gen 2	

Abstract of Issue: New inspections have brought to light additional concerns regarding the safety of the Ice Bumper Cars. Previous testing concluded that the G-force experienced during the ride was sufficiently low to waive the seat belt requirement. It has been brought to our attention that there are additional safety concerns that seat belts will help mitigate. Seat belts will ensure that all riders stay seated properly in the car during operation.

Reason for Release: The state of Colorado performed an inspection on this ride at a location in Denver. A third party inspector and the state authority deemed it mandatory for the ride to have seat belts.

Action To Be Taken: Seat belts shall be installed on all bumper cars going forward. Parts and mounting instructions can be obtained from Ice Bumper Cars International.

Details of Issue: Exiting the ride prematurely presents a serious safety concern. Seat belts will be used to ensure riders stay seated in the cars at all times during ride operation.