



Worldwide Safety Group Inc.

4307 US Hwy 92W

Plant City, FL. 33563

813-505-3938

avery@worldwidesafetygroup.com

October 5, 2020

To all owners of KMG Freak Out Rides,

It has come to our attention that a 2004 KMG Freak Out ride has had a sweep attachment bracket break off from the center hub during disassembly of the ride.

We encourage all owners / operators to have your ride inspected by a qualified individual to look for indications and if any are found to have additional nondestructive testing performed to verify the findings.

We have been informed that the Manufacturer is aware of this and is working with the owner of this particular ride to sell them a replacement hub. The Ride Manufacturer however has not issued any bulletin or acknowledgment to inform owners of this ride to look for this potential issue.

Out of an abundance of caution and to maintain "Safety Through Communication" we want to let our industry owners and inspectors know of this issue and encourage them to look at their rides for any indications.

If indications are found, please do not operate the ride and contact the manufacturer for instructions.

Please see the pictures below for the areas of concern this is the lower attachment area of the sweeps to the center hub.



Respectfully Submitted,

Avery L. Wheelock

Avery L. Wheelock - President

Worldwide Safety Group, Inc.