



[click here to return to the member index](#)

American Superior Lighting

— SERVICE BULLETIN —

ATTN: SHOW OWNERS

POST THIS BULLETIN FOR ALL MAINTENANCE PERSONNEL.

THE ULTRALIGHT LENS ASSEMBLY IS A SNAP CAP DESIGN

<p>STEP 1 - INSERT TOOL <i>(Pocket Screw Driver, Pocket Knife, etc.)</i></p>	<p>STEP 2 - TWIST TOOL AND SEPARATE LENS</p>	<p>STEP 3 - EASY BULB REPLACEMENT</p>
<p>PROBLEM: Black socket ring has premature cracking or breakage due to improper lens removal for bulb replacement.</p>		<p>SOLUTION: Removal of lens cap only. A pocket tool will be provided FREE OF CHARGE from ASI. Just call 614/266-2959 today!</p>

American Superior Lighting
1506 Fernwood Road
Wintersville, OH 43952

Eric Bates

AIMS Member since 12/3/96



Click on the logo to return to AIMS' homepage.

Copyright © 1996-1999, AIMS International. All Rights Reserved.
Web page maintained by AIMS webmaster

!

Counter reset March 19, 1999

This page was last updated...
Thursday, 19-Aug-99 18:21:06 GMT.