## Majestic Manufacturing, Inc.

Majestic Manufacturing, Inc. \* PO Box 128 4536 State Route 7, New Waterford, Ohio 44445

Subject: Musik Express Aluminum Track

## ATTN: OWNER/OPERATOR

This bulletin pertains to the operation of your Majestic unit. This Service Bulletin <u>must</u> remain with the owner's manual at <u>all</u> times. If you have any questions regarding the Bulletin, contact our office at 330/457-2447, M-F 8:00a.m. -4:30p.m. E.S.T. \*\* Fax 330/457-7490.

## SERVICE BULLETIN

**Date:** August 30, 2001

S.B. Number: 2001-02

## Notice:

This bulletin pertains to the safe operation of your Musik Express.

It has come to our attention that cracks have developed on the aluminum track where one track is bolted to the other.

The owner/operator must inspect the area around the singe bar (see diagram). If cracks are visible, they MUST be re-welded.

If you have any questions on factory standards or procedures on our equipment, contact Majestic Manufacturing, Inc. during normal business hours of 8:00 a.m. to 4:30 p.m. Monday through Friday, E.S.T. at 330/457-2447 or toll free at 1-888-MAJ-RIDE.

