

# Majestic Manufacturing, Inc.

Majestic Manufacturing, Inc. \* PO Box 128  
4536 State Route 7, New Waterford, Ohio 44445

Subject: Music Express Center Star Inspection

## ATTN: OWNER/OPERATOR

This bulletin pertains to the operation of your Majestic unit. This Service Bulletin must remain with the owner's manual. If you have any questions regarding the Bulletin, contact our office at 330/457-2447, M-F 8:00a.m. -4:30p.m. E.S.T. \*\* Fax 330/457-7490.

## SERVICE BULLETIN

Date: September 9, 1999

S.B. Number: 99-4

### Notice:

In a continuing effort to strive for safety, this service bulletin is for all Musik Express units. This is to inform the owners and operators that the folding star should be inspected so that it does not become detached from the ride while the ride is in operation.

The folding star is suspended from the rafters of the Musik Express. The star acts as part of the lighted scenery and makes a false ceiling over the riders. Inspect the star daily before start-up of the ride and periodically during ride operation.

### Important areas of inspection:

- All Safety bolts through the aluminum channel and plastic cover are tight and secure.
- The telescoping end is not worn or broken.
- The outside perimeter is securely attached with the proper pins and safety cables.
- If unsure about each and every inspection point, call Majestic Manufacturing.

If any of these areas present excessive wear or missing parts, **immediate** repair is necessary.

If you have any questions on factory standards or procedures on our equipment, contact Majestic Manufacturing, Inc. during normal business hours of 8:00 a.m. to 4:30 p.m. Monday through Friday, E.S.T. at 330/457-2447.