

ZAMPERLA INC.
49 Fanny Road
Parsippany, New Jersey 07054-6545
USA
Phone: 973 334 8133 Fax: 973 334 6880

Bulletin No: 99 CB1
Release Date: 06/28/99
Effective Date: 06/28/99
Supersedes:
Completion Date: As soon as possible
Page: 1 of 5

SERVICE BULLETIN

Ride Manufacturer: Zamperla Inc.	Affected Production Dates: from 1990 to 1995
Ride Name: Crazy Bus	Affected Serial Nos.: See attached list of serial numbers
Model Number: Crazy Bus	

Abstract Of Issue:

Cracks have been found in the welds of the flange that connects the rotating hub to the counterweight arm on the gondola side. See areas indicated on the accompanying diagram.

Reason For Release:

Same.

Action To Be Taken:

Magnetic particle testing by a certified NDT technician.

Detail Of Issue:

If cracks have been detected in the above mentioned welds and confirmed, please stop the ride and immediately contact Zamperla for notification of repair procedure.

Future Action To Be Taken:

Magnetic particle testing by a certified NDT technician annually.